


Section III. Assembly & Installation Instructions

Discharge Chute Installation

(Fig. P1)

1. A standard discharge chute consists of a two piece mounting bracket on each side and a chute. The mounting brackets are mounted at the discharge end of the conveyor, one on each side.
2. A two piece bracket should be mounted on each side of the conveyor. (Fig. P1) The discharge chute will then be slid on over the lower brackets. (Fig. P2) The chute bracket bolts and two mounting bracket bolts can then be tightened to hold chute in desired location.



(Fig. P2)