

## OD Gripping Air Hands

- The amount of inflation and grip force can be adjusted as needed with the use of a pressure regulator (see page 1014).
- Choose silicone when high-temperature and non-marking is most important, Neoprene when part temperature is lower and long-life is most important.
- Dimensional drawings online.



### OD Gripping Air Hands

Quick#	Part#	Price	Material	Part Range Ø ID	ØA (Deflated)	Maximum Restricted Pressure	Maximum Unrestricted Pressure	Wt.
1319	GSG-OAH-15N	\$552.00	Neoprene (up to 165°F)	5-15	19	20psi	10psi	60g
1320	GSG-OAH-25N	\$629.00		10-25	27			145g
1321	GSG-OAH-35N	\$783.00		15-35	37			210g
1322	GSG-OAH-45N	\$878.00		20-45	48			285g
1323	GSG-OAH-15S	\$848.00	Silicone (up to 320°F)	5-15	19	15psi	7.5psi	60g
1324	GSG-OAH-25S	\$926.00		10-25	27			145g
1325	GSG-OAH-35S	\$1,004.00		15-35	37			210g
1326	GSG-OAH-45S	\$1,330.00		20-45	48			285g

### Mounting Brackets for OD Air Hands

Quick#	Part#	Price	Use with	Wt.
1739*	GSC-OAH-15MB	\$39.45	OAH-15	31g
1740*	GSC-OAH-25MB	\$39.45	OAH-25	46g
1741	GSC-OAH-35MB	\$39.87	OAH-35	57g
1742	GSC-OAH-45MB	\$44.75	OAH-45	69g



Order profile mounting fasteners separately  
(2x) M5x10, slotted nut & washer, see page 1077.  
\*Use M5 slotted nut (Q#4951) to fasten brackets #1739 & #1740 to Gimatic & ASS profile on page 1078.

### Application Examples

