


SECTION III. ASSEMBLY & INSTALLATION INSTRUCTIONS CON'T.

Discharge Chute Installation



(Fig. 45)

A standard discharge chute consists of two mounting brackets and a discharge chute. The mounting brackets are mounted at the discharge end of the conveyor, one on each side.

(Fig. 45)



(Fig. 46)

Before tightening the bolts, mount the discharge chute in one of the holes in the brackets, whichever works best for your application. Use the 3/8-16 x 1" bolts provided. Tighten up all bolts in the brackets, then adjust the chute to desired location and tighten bolts to lock the chute into place. (Fig. 46)